


Figure 1



THE LIFE CYCLE APPROACH

Figure 2A

0095543-002401





Figure 2B



1041230 E4B5E650




Figure 3




Figure 4




Figure 5

104280" 54855660

Trim 2000

Task Options

☐ All
☒ Open Tasks
☐ Scheduled Tasks
☐ Completed Tasks
☐ Canceled Tasks

Task Type

All
 Maintenance
 Repairs
 Replace
 Restore
 Services
 Misc

Building	Roof	Type	Task	Schd
Building 3	Roof 3	Maintenance	Good, Maintain Roof	//
Building 3	Roof 3	Maintenance	Good, Maintain Roof	//
Building 3	Roof 3	Maintenance	Good, Maintain Roof	//
Building 3	Roof 3	Repairs	Repairs Required, Minor	//
Building 3	Roof 3	Repairs	Repairs Required, Minor	//
Building 3	Roof 3	Repairs	Repairs Required, Minor	//
Building 3	Roof 3	Repairs	Repairs Required, Major	//
Building 3	Roof 3	Restore	Restore Immediate	//

Figure 6

0035843.082401

TRIM REPORT: ABC Company

☐ **TRIM Report**

- ☐ Cover
- ☐ Cover with Photos
- ☐ Report Interpretation
- ☐ Table of Contents
- ☐ INTRODUCTION
- ☐ EXECUTIVE SUMMARY - Table of Contents
- ☐ Overview
- ☐ Roofing Inventory Examined
- ☐ Roof Membrane Distribution
- ☐ Square Footage Distribution
- ☐ Age Analysis
- ☐ Urgency Categories
- ☐ Roof Type Analysis
- ☐ Budget Summary
- ☐ Budget Detail (By Building)
- ☐ Budget Detail (By Roof)

☐ **Region - None**

- ☐ None Cover Page
- ☐ None Cover Page with Photos

☒ Current Inspection

Figure 7

Trim 2000

No	Priority	Type	Scope
1	1 Immediate	Repairs	Repair at Perim
2	1 Immediate	Repairs	Repair at Laps
3	1 Immediate	Repairs	Fill Pitch Pocket
4	1 Immediate	Repairs	Re-secure Cou
5	1 Immediate	Repairs	Remove Sealar
6	1 Immediate	Repairs	Reseal Laps
7	1 Immediate	Repairs	Reseal Coping
8	1 Immediate	Repairs	Coat Flashings
9	1 Immediate	Repairs	Clean Debris
10	1 Immediate	Repairs	Repair Blisters
11	1 Immediate	Repairs	Spud Gravel
12	1 Immediate	Repairs	Strip in Single P

Customized text

Repair membrane voids and fractures at the perimeter.

Order ☒ Number ☐ Priority

Figure 8